




Subject: Service Champ Cartridge filter CF5839

Ref: 2017 Buick Encore 1.4L 4 cyl

The 2017 Buick Encore with 1.4L engine may come from the factory with one of two oil filter adapters (OFA). These two adapters are identical in outward appearance with the exception of the vendor name on the cast aluminum housings and the injection molded nylon caps. They DO NOT use the same cartridge filters. See Photo below.



HENGST is on left, UFI is on right.

The most common OFA is manufactured by and has the name HENGST in raised letters on the cast aluminum housing and nylon cap. These housings use the ACDelco PF2257G / Service Champ CF5839 cartridge.

The other housing is made by UFI as identified on the housing and cap. The UFI housing uses ACDelco PF2263G / Service Champ TBD. See photo below.



Hengst housing cartridge on left, UFI on right.

**Engine and equipment manufacturer's warranties remain
in effect when using Service Champ filters**

For more information or purchase, please call Technical Services at 1-800-882-0890 Champion Laboratories is an ISO/TS16949 registered company. The information contained herein is intended to be used as an indication of performance and is not meant to be used as an exact specification. The information is based upon test data and is subject to test and material variability. Changes may occur based upon technology, process and material innovation as Champion Laboratories strives to attain the highest levels of performance and customer satisfaction. These changes may occur without notification.