



## OIL FILTER BULLETIN HYUNDAI Sonata 3.3L 06-07


This application is covered by the following oil filters;

Service Champ# CF5610  
Warner# WP972  
Security# CH-9999

### O-Ring Replacement & Housing Cap Torque

During replacement of the oil filter, it is important to also replace the included O-rings. Please, follow instructions in the vehicle manufacturer's manual or as directed on the oil filter housing cap and tighten housing cap to specified torque, which is 24.5 N/m (18.1 ft/lbs).

Warning – Failure to replace the gaskets and tighten the housing cap as specified by the vehicle manufacturer may result in engine damage.



Service Champ recommends cap wrench #A266 and torque wrench #3460 to facilitate installation.